



10. White cast iron contains carbon in the form of  
 free carbon       graphite       cementite       ferrite
11. Eutectoid steel contains following percentage of carbon  
 0.02 %       0.3 %       0.63 %       0.8 %
12. Inconel is an alloy of  
 nickel, chromium and iron       nickel and copper  
 nickel and zinc       nickel and lead
13. Which is false statement about annealing. Annealing is done to  
 relieve stresses       harden steel slightly  
 soften material       permit further cold working
14. Charpy test is conducted to measure  
 hardness       fracture stress  
 fatigue resistance       brittleness
15. Iron alloyed with carbon up to 2 % is called  
 cast iron       steel       iron alloy       mild steel
16. Cooling during Normalizing is carried out in  
 furnace       air       water       oil
17. Which of the following is non-destructive test?  
 tensile test       impact test  
 charpy test       radiography test
18. Euctectoid composition of carbon steel at room temperature is known as  
 pearlite       ferrite       cementite       martensite
19. Pearlite is combination of  
 ferrite and cementite       ferrite and austenite  
 ferrite and iron graphite       cementite and gamma iron
20. The transistor is made of  
 silver       gold       German silver       germanium

SECTION "B"


Attempt **ALL** questions. Assume suitable data if necessary.

Q. N. 1

- a. Steel is often coated with a thin layer of zinc if it is to be used outside. What characteristics the zinc provides to this coated, or galvanized, steel. [2]
- b. For each of the following classes of materials, give two specific examples that are a regular part of your life: metals, ceramics, polymers, semiconductors. [2]

Q. N. 2

- a. Define the terms: Allotropy, Metallic glasses, Liquid crystals, and Glass ceramics. [4×0.5 =2]
- b. Write down the procedure for finding Miller Indices of a direction and apply the procedure to determine Miller indices of directions *A*, *B*, and *C*. [3]



Q. N. 3


- a. Describe any three types of point defects. [3]
- b. Explain the significance of dislocations. [1]

Q. N. 4

- a. Draw qualitative stress - strain curve for a ductile metal and label the diagram properly. Compare the curve with curve for glass. [3]
- b. What is hardness? Describe the Brinell hardness test in detail. [2]
- c. Describe briefly, with a proper sketch, ductile fracture in metallic materials. [2]

Q. N. 5

- Draw and describe cooling curve for pure metal with no inoculation. How does it differ from cooling curve for metals with inoculation? [3]
- A 5 cm diameter sphere solidifies in 1050 s. Calculate the solidification time for a 0.3 cm x 10 cm x 20 cm plate cast under the same conditions. Assume that  $n = 2$ . [2]
- Applying lever rule determine the composition of each phase in a Cu-40 % Ni alloy at 1270 °C. [3]



Q. N. 6

- Draw a self-explanatory iron-iron carbide phase diagram showing all the important phases and reactions. [3]
- With reference to iron-iron carbide diagram describe Full Annealing, Normalizing, Process Annealing and Spheroidizing. [4×1 = 4]
- Describe Tempering heat treatment process. Why is it performed? [2]

Q. N. 7

- Write down two most important properties of ceramics. [1]
- Write short notes on: Applications of Brass, Refractories. [2×1 = 2]