

02 MAY 2023

KATHMANDU UNIVERSITY  
End Semester Examination [C]  
April/May, 2023

Marks Scored:

Level : B.E.

Year : II

Exam Roll No. :

Time: 30 mins.

Course : MEEG 217

Semester : I

F. M. : 20

Registration N.:

Date :

SECTION "A"  
[20Q. × 1 = 20 marks]

Choose and mark [×] in the most appropriate option.

- For a ductile material , toughness is a measure of  
 Resistance to scratch  Ability to absorb energy up to fracture  
 Ability to absorb energy till elastic limit  Resistance to indentation.
- When temperature of solid metal increases,  
 Strength of metal decreases but ductility increase  
 Both the strength and ductility of metal decreases  
 Both the strength and ductility of metal increases  
 Strength of metal increases but ductility decreases
- For casting of turbine blades made of high temperature and high strength alloys, the most suitable process is  
 Semi centrifugal casting  Investment casting  
 Centrifugal casting  Slush casting
- A moving mandrel is used to  
 Wire drawing  Tube drawing  Metal cutting  Forging
- In rolling process, the state of stress of material undergoing deformation is  
 Pure compression  Pure shear  
 Shear and compression  Tension and shear
- Penetration is increased by  
 Increasing welding speed and current  
 Increasing current and decreasing speed  
 Decreasing speed and current  
 Increasing speed and decreasing current
- In DC welding, Straight Polarity (Electrode negative) results in  
 Lower penetration.  Lower deposition rate.  
 Less heating of work piece  Smaller weld pool
- The size of BUE in Metal cutting increases with  
 Very high speed  Large uncut chip thickness.  
 Use of cutting fluid  Increase in Positive rake angle.
- BUE is formed while machining  
 Ductile material with high speed  Ductile material with low speed  
 Brittle material with high speed  Brittle material with low speed

10. Fluxes used in welding in order to protect the molten metal and the surfaces to be joined from  
 Oxidation       Carburizing       Dirt       Distortion and warping
11. Metal Deposited on to the work piece from the electrode  
 is forced across the arc  
 falls because of gravity  
 is attracted towards the work piece due the positive polarity of the work piece  
 is attracted towards the work piece due to the negative polarity of the work piece
12. In arc welding operations the current value is decided by  
 Thickness of plate       Size of the electrode.  
 Voltage across the arc       Speed of travel
13. Two M.S. plates, 20 mm thick for boiler drum are to be butt welded. Which of the following processes would be best suited ?  
 Submerged arc welding       Electro slag welding.  
 Electric resistance welding       TIG/MIG welding
14. Chvorinov's Rule states that total solidification time is proportional to which one of the following quantities?  
  $(A/V)^n$         $H_f$   
  $V/A$         $(V/A)^2$   
*where A = surface area of casting,  $H_f$  = heat of fusion,  $T_m$  = melting temperature, and V = volume of casting.*
15. Given that  $W_m$  = weight of the molten metal displaced by a core and  $W_c$  = weight of the core, the buoyancy force is which one of the following?  
 downward force =  $W_m + W_c$        downward force =  $W_m - W_c$   
 upward force =  $W_m + W_c$        upward force =  $W_m - W_c$
16. Which of the following rolling mill types are associated with relatively small diameter rolls in contact with the work?  
 Cluster mill       Continuous rolling mill  
 Reversing mill       Three-high configuration.
17. Which of the following bulk deformation processes are not involved in the production of nails for lumber construction?  
 Bar and wire drawing       Extrusion  
 Forging       Rolling
18. Milling machine is classified as horizontal or vertical type, depending on the position of  
 Spindle       Work piece       Milling Cutter       Work table or bed
19. Shrinkage allowance on pattern is provided for  
 Compensation for finishing operation after completion of casting  
 Easy removal of casting  
 Compensation for shrinkage during solidification  
 Compensation for shrinkage after solidification
20. What is the type of welding defect caused due to poor deposition of weld rod is called?  
 Porosity       Undercut       Under fill       Crack


Level : B.E.  
Year : II  
Time : 2 hrs. 30 mins.

Course : MEEG 217  
Semester : I  
F.M. : 55

SECTION "B"

Attempt *ALL* questions. Assume data if necessary.

1. Elaborate the various stages in product design process. What are the different factors influencing manufacturing of a product? [3+2]
2. Compare three different materials: Mild steel, Aluminum and Cast iron with the help of Stress Strain Diagram. Referring the diagram, Describe the behavior of the each material with key terms? [3+2]
3. A strip of Metal is originally 1.5 m long .It is stretched in three steps: First to a length of 1.75 m, then to 2.0 m, and finally 3.0 m. Show that the total true strain is the sum of the true strains in each step, i.e., that the strains are additive. Show that, using engineering strains, the strain for each step cannot be added to obtain the total strain. [5]
4. Describe the basic working principle and important parts of Lathe machine. What are the different operations performed on lathe machine? Explain each operation with illustrative figures. [3+4]
5. How is arc obtained in arc welding, Write different power sources used in the welding with their application? Draw a labeled diagram of three types of Oxy-acetylene gas welding flames with their applications. [3+3]
6. What is Destructive and Nondestructive testing in welded joint? Two similar material plates were welded together and tested, "it was found that the welded joint were stronger than of the parent material". Do you think that the above statement is incorrect? Do explain with valid reason. [2+2]
7. In a Given arc welding operation, the power source is at 20 V and current is 300 A. If the electrode travel speed is 9 mm/sec, calculate the CSA of joint. The overall heat transfer efficiency of the process is 75%. Heat required to melt the steel is 10 J/mm<sup>3</sup>. [4]
8. What is the ideal profile of sprue? Explain how it is principally governed and actually practiced? Draw labeled diagram of a mould box showing pattern, gates, runner and riser. What do you understand by directional solidification of casting? [1+2+3]
9. In the casting of steel under certain mold conditions, the mold constant in Chvorinov's Rule is known to be  $C_m = 4.0 \text{ min/cm}^2$ , based on previous experience. The casting is a flat plate whose length = 30 cm, width = 10 cm, and thickness = 20 mm. Determine how long it will take to solidify. [5]
10. For hot working, it is often necessary to heat the work piece in a furnace and there are scale losses and other problems. Why is hot working sometimes preferred over cold working in spite of such disadvantages? With Illustrative labeled diagram, compare similar product manufactured by Forging, forming, casting and machining with the help of mechanical properties and grain structures. [3+5]



02 MAY 2023

KATHMANDU UNIVERSITY  
End Semester Examination [C]  
April/May, 2023

Marks Scored:

Level : B.E.

Year : II

Exam Roll No. :

Time: 30 mins.

Registration N. :

Course : MEEG 213

Semester : I

F. M. : 20

Date :

SECTION "A"

[20Q. × 1 = 20 marks]

Choose and mark [X] in the most appropriate option.

- Which of these materials have typically higher strength?  
 Silicon Carbide Ceramics                       Carbon Epoxy Composites  
 Carbon Metal Alloys                                 Glass Polyester
- Calculate the number of electrons capable of conducting an electrical charge in 15 cubic centimeters of silver. Given: density of silver = 10.49 g/cm<sup>3</sup>, atomic mass of silver = 107.868 g/mol, Avogadro's number = 6.023E23, atomic number of silver = 47  
  $8.79 \times 10^{22}$               $8.79 \times 10^{23}$               $8.79 \times 10^{24}$               $8.79 \times 10^{25}$
- For monoclinic crystal system, edge lengths (a, b and c) and inter-axial angles ( $\alpha$ ,  $\beta$ , and  $\gamma$ ) are .....  
  $a = b \neq c, \alpha = \beta = 90^\circ, \gamma = 120^\circ$       $a = b = c, \alpha = \beta = \gamma \neq 90^\circ$   
  $a \neq b \neq c, \alpha = \beta = \gamma = 90^\circ$               $a \neq b \neq c, \alpha = \beta = 90^\circ \neq \gamma$
- What is atomic packing factor of BCC crystal structure?  
 0.68                       0.52                       0.74                       0.32
- What is the approximate optimal grain size for highest yield strength?  
 1 nm                       10 nm                       100 nm                       0.1 nm
- For a specimen with ASTM grain size number of 6.5, how many grains per square inch will be there at a magnification of 70x?  
 9.236 grains/in<sup>2</sup>                                       22.17 grains/in<sup>2</sup>  
 92.36 grains/in<sup>2</sup>                                       2.217 grains/in<sup>2</sup>
- Which of the following is **NOT TRUE** for a tie line?  
 Tie line is used to determine different phases present  
 Tie line is used to the composition of phases present  
 Tie line is used to determine the mass fraction of phases present  
 Tie line is used to determine the volume fraction of phases present
- Calculate number of atoms in a critical nucleus when solid Pb forms by homogeneous nucleation. ( $a_0 = 0.3615 \text{ nm}$  for FCC, solid-liquid interfacial energy =  $33 \times 10^{-7} \text{ J/cm}^2$ , freezing temperature =  $327^\circ\text{C}$ , heat of fusion =  $237 \text{ J/cm}^3$ , undercooling for nucleation =  $80^\circ\text{C}$ )  
 1616                       808                       3232                       40

9. Increase in temperature of an undercooled uninoculated liquid metal as a result of liberation of heat during nucleation is called .....  
 thermal arrest     recalescence     superheat     solidification
10. A three-phase reaction in which two solids transform into one solid on cooling is known as .....  
 peritectic     eutectoid     monotectic     peritectoid
11. During solidification, ..... austenite transforms into ..... ferrite.  
 FCC, BCC     BCC, FCC     FCC, SC     SC, BCC
12. Annealing is done ..... upper critical temperature for hypoeutectoid steels and ..... upper critical temperature for hypereutectoid steels.  
 above, below     above, above     below, above     below, below
13. Ductility is the highest for .....  
 fine pearlite     coarse pearlite     bainite     martensite
14. .... is never obtained with continuous cooling.  
 fine pearlite     coarse pearlite     martensite     bainite
15. .... are used in cutleries.  
 medium carbon steels     high carbon steels  
 mild steels     low carbon steels
16. Which of these uses spherical steel indenter?  
 Vickers hardness     Rockwell hardness  
 Brinell hardness     Knoop hardness
17. Chevron markings in the failed material indicates .....  
 ductile fracture     brittle fracture  
 fatigue fracture     corrosion failure
18. Closely packed striations represent .....  
 low stress, many cycles     high stress, few cycles  
 brittle fracture     crack origin
19. In which type of point defect, positive and negative ions are missing from the crystal?  
 Vacancy     Interstitial     Schottky     Substitutional
20. The highest relative length of stream in spark test is seen in .....  
 Aluminum     White cast iron     High speed steel     Wrought Iron